



Bound Brook Centerline (RM) Dams (Natural and Manmade) Pipes Crossing the Brook Shoreline Former Cornell Dublier Electronics Facility T1-A Sample Location ID

Panel A

Texture

Fine Sand

Silt

Coarse Sand O Silt with Clay Coarse to Fine Sand Clay with Silt Coarse to Medium Sand

Medium to Fine Sand

Cobbles Gravel

Hard Bottom

New Market Pond Sand as interpreted by the side scan sonar Rock-Gravel-Sand as interpreted by the side scan sonar

Silt as interpreted by the side scan sonar

Panel B

Depth Advanced Depth to Refusal (ft.) Without Refusal* (ft.)

0.0 - 1.0 0.0 - 1.0 **1.1 - 2.0** 1.1 - 2.0 2.1 - 3.0 2.1 - 3.0 **O** 3.1 - 4.0 <u>△</u> 3.1 - 4.0 **4**.1 - 5.0 4.1 - 5.0 > 5.1 5.1 - 6.5


*Probe rod not long enough to accommodate water depth and to encounter refusal.

Sources:

- 1) Background Data Street Information, NJDOT, 2012; Streams, NJDEP, 2002.
- 2) Shoreline was adapted from a Tetra Tech, Inc. shoreline shapefile, which was adjusted to be consistent with information collected in the field, aerial imagery provided by Penoni Associates, Inc., and 2002 aerial imagery from the New Jersey Office of Information Technology (Office of GIS).
- 3) "Hard bottom" is a generic term that covers all types of hard material that the probe rod could not penetrate (e.g., cinderblocks, rip-rap, bedrock, rock, or hard debris). Only exposed bedrock at the surface can be visually identified and confidently classified as "weathered, fractured bedrock."




KEY MAP Sediment Probing Interpretation Bound Brook OU4 RI/FS




South Plainfield, New Jersey

Bound Brook OU4 RI/FS


Figure 3-2 Sheet 2 of 11








Bound Brook OU4 RI/FS

Figure 3-2 Sheet 4 of 11















Panel A: Surface Sediment Texture and Panel B: Depth of Refusal Bound Brook OU4 RI/FS


Figure 3-2 Sheet 8 of 11














Bound Brook OU4 RI/FS


Figure 3-3 Sheet 2 of 6





















CORNELL-TOP - LBG.GDT - 10/31/12 11:06 - C:\\




CORNELL-TOP - LBG.GDT - 10/31/12 15:42 - C:\USEF


THE Louis Berger Group, INC.

2014


3-4d




CORNELL-TOP - LBG.GDT - 10/25/12




CORNELL-TOP - LBG.GDT - 10/10/12 14:30 - C:\USERS\F





CORNELL-TOP - LBG.GDT - 10/11/12 12:09 - C:\USERS\PUB







CORNELL-TOP - LBG.GDT - 10/22/12 14:31













Cornell-Dubilier Electronics
Superfund Site
South Plainfield, New Jersey


CD RAA Sampling Results
Bound Brook OU4 RI/FS


2014


Figure 3-6














Superfund Site

South Plainfield, New Jersey

2014

Figure 3-10





Exposure Units for the OU4 Risk Assessment Bound Brook OU4 RI/FS

Figure 3-11